



Eight tracks to GD&T expertise

Quality & measurement—6 tracks



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians



Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.

Eight tracks to GD&T expertise

Quality & measurement—6 tracks

Seminars

GD&T LEVEL E

Learn how GD&T affects your bottom line

GD&T LEVEL 1

Learn to understand engineering drawings & perform print reviews

GD&T LEVEL 2

Learn how to correctly interpret GD&T symbols

GD&T LEVEL 3

Learn to apply physical measurement principles to 1D & 2D measurements

GD&T LEVEL 4

Go beyond the fundamentals of GD&T

GD&T LEVEL 5

Get a better understanding of 3D measurement systems, including a critical view of Gage R&R

GD&T LEVEL 6

Learn how to improve tolerancing on individual components and sub-assemblies

GD&T LEVEL 7

Achieve a firm understanding of measurement uncertainty per ASME B89.7.2 -2007

Tracks

Executive 1 **4**

Manager 2
Introduction 3
Fundamentals 4
Applications 5
Systems 6
Analysis 7
Command 8

Executive Overview

Introduction to Mechanical Drawings & GD&T

GD&T - Intermediate Principles **24**

Introduction to Dimensional Metrology

GD&T - Advanced Applications **56**

Applied Dimensional Metrology **72**

GD&T - Tolerancing Optimization & Analysis

Measurement Uncertainty **104**

4 Hours

8 Hours

16 Hours

16 Hours

16 Hours


16 Hours

16 Hours

16 Hours

Job Path / Responsibility

- 1 Directors, VPs, GMs**
- 2 Managers**
- 3**
- 4 Non-mechanical quality engineers & machine operators**
- 5 Measurement technicians, mechanical inspectors**
- 6 Senior quality technicians**
- 7**
- 8 Quality engineers, precision measurement engineers, statisticians**



Dr. Greg Hetland
Phone: (612) 670-9311
Fax: (612) 395-5405
www.iigdt.com

IIGDT
7400 Edinborough Way,
#5208
Edina, MN 55435 U.S.A.

Eight tracks to GD&T expertise

Quality & measurement—6 tracks

Seminars

GD&T LEVEL E

Learn how GD&T affects your bottom line

GD&T LEVEL 1

Learn to understand engineering drawings & perform print reviews

GD&T LEVEL 2

Learn how to correctly interpret GD&T symbols

GD&T LEVEL 3

Learn to apply physical measurement principles to 1D & 2D measurements

GD&T LEVEL 4

Go beyond the fundamentals of GD&T

GD&T LEVEL 5

Get a better understanding of 3D measurement systems, including a critical view of Gage R&R

GD&T LEVEL 6

Learn how to improve tolerancing on individual components and sub-assemblies

GD&T LEVEL 7

Achieve a firm understanding of measurement uncertainty per ASME B89.7.2 -2007

Tracks

Executive 1

Manager 2

Introduction 3

Fundamentals 4

Applications 5

Systems 6

Analysis 7

Command 8



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians




Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.


Eight tracks to GD&T expertise

Quality & measurement—6 tracks



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians



Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.

Eight tracks to GD&T expertise

Quality & measurement—6 tracks

Seminars

GD&T LEVEL E

Learn how GD&T affects your bottom line

GD&T LEVEL 1

Learn to understand engineering drawings & perform print reviews

GD&T LEVEL 2

Learn how to correctly interpret GD&T symbols

GD&T LEVEL 3

Learn to apply physical measurement principles to 1D & 2D measurements

GD&T LEVEL 4

Go beyond the fundamentals of GD&T

GD&T LEVEL 5

Get a better understanding of 3D measurement systems, including a critical view of Gage R&R

GD&T LEVEL 6

Learn how to improve tolerancing on individual components and sub-assemblies

GD&T LEVEL 7

Achieve a firm understanding of measurement uncertainty per ASME B89.7.2 -2007

Tracks

Executive 1

Manager 2

Introduction 3


Fundamentals 4

Applications 5

Systems 6

Analysis 7

Command 8



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians



Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.

Eight tracks to GD&T expertise

Quality & measurement—6 tracks

Seminars

GD&T LEVEL E

Learn how GD&T affects your bottom line

GD&T LEVEL 1

Learn to understand engineering drawings & perform print reviews

GD&T LEVEL 2

Learn how to correctly interpret GD&T symbols

GD&T LEVEL 3

Learn to apply physical measurement principles to 1D & 2D measurements

GD&T LEVEL 4

Go beyond the fundamentals of GD&T

GD&T LEVEL 5

Get a better understanding of 3D measurement systems, including a critical view of Gage R&R

GD&T LEVEL 6

Learn how to improve tolerancing on individual components and sub-assemblies

GD&T LEVEL 7

Achieve a firm understanding of measurement uncertainty per ASME B89.7.2 -2007

Tracks

Executive 1

Manager 2

Introduction 3


Fundamentals 4

Applications 5

Systems 6

Analysis 7

Command 8



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians



Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.

Eight tracks to GD&T expertise

Quality & measurement—6 tracks

Seminars

GD&T LEVEL E

Learn how GD&T affects your bottom line

GD&T LEVEL 1

Learn to understand engineering drawings & perform print reviews

GD&T LEVEL 2

Learn how to correctly interpret GD&T symbols

GD&T LEVEL 3

Learn to apply physical measurement principles to 1D & 2D measurements

GD&T LEVEL 4

Go beyond the fundamentals of GD&T

GD&T LEVEL 5

Get a better understanding of 3D measurement systems, including a critical view of Gage R&R

GD&T LEVEL 6

Learn how to improve tolerancing on individual components and sub-assemblies

GD&T LEVEL 7

Achieve a firm understanding of measurement uncertainty per ASME B89.7.2 -2007

Tracks

Executive 1

Manager 2

Introduction 3

Fundamentals 4

Applications 5

Systems 6


Analysis 7

Command 8



Job Path / Responsibility

- 1 Directors, VPs, GMs
- 2 Managers
- 3
- 4 Non-mechanical quality engineers & machine operators
- 5 Measurement technicians, mechanical inspectors
- 6 Senior quality technicians
- 7
- 8 Quality engineers, precision measurement engineers, statisticians



Dr. Greg Hetland
 Phone: (612) 670-9311
 Fax: (612) 395-5405
 www.iigdt.com

IIGDT
 7400 Edinborough Way,
 #5208
 Edina, MN 55435 U.S.A.